

# SERVICE - INFO



**LuK Nr: 133 0608 10 – 330mm DBFP  
133 0271 10 – 330mm TBFR**

**Bulletin 988 2000 600**

**NEW HOLLAND FORD – 3000, 4000, 5000 Series & Industrial \*\***

<b>Info:</b>	<b>133 0608 10 replaces / ersetzt / remplace / sustituye a / sostituisce 133 0018 10 133 0271 10 replaces / ersetzt / remplace / sustituye a / sostituisce 133 0017 10</b>
<b>(GB)</b>	When replacing a 4 lever coil spring clutch with LuK diaphragm type clutch, shims are not required.
<b>(D)</b>	Wenn die 4-Hebel-Schraubenfederkupplung durch eine LuK-Tellerfederkupplung ersetzt wird, entfallen die Segmentbleche.
<b>(F)</b>	Le remplacement d'un embrayage à ressorts hélicoïdaux à 4 leviers par un embrayage à diaphragme LuK ne requiert pas de cales de réglage.
<b>(E)</b>	Al reemplazar el embrague de muelles helicoidales con 4 patillas por el de diafragma no es necesario colocar calzos.
<b>(I)</b>	Quando si sostituisce una frizione a molle elicoidali a 4 leve con una frizione di tipo a diaframma LuK, non sono necessari distanziatori.

\*\* For model information please see LuK Catalogue / Die genaue Fahrzeugzuordnung entnehmen Sie bitte dem LuK-Katalog / Pour les informations le modèle veuillez consulter le catalogue LuK / Para obtener información sobre el modelo, rogamos consulte el catálogo de LuK / Per informazioni sul modello consultare il catalogo LuK

**133 0018 10**



**133 0608 10**



**133 0017 10**



**133 0271 10**



Issue Level 3

**LuK Aftermarket Service UK Ltd.**  
Holme Lacy Road, Rotherwas  
HR2 6LA Hereford · The United Kingdom  
Phone: +44 1432 264264 · Fax +44 1432 275146  
e-mail: LuK-AS.uk.pm@schaeffler.com  
**A Member of the Schaeffler Group**

