

# SERVICE - INFO



**LuK Nr: 630 2461 09 – 280/295mm TGU6**

**Bulletin 988 2000 990**

**STEYR – M975, M986, 955, 964, 970E, 975 & 8070**

<b>Info:</b>	<b>630 2461 09 Replaces / ersetzt / remplace / sustituye a / sostituisce 230 0030 20</b> <b>630 2461 09 Replaces / ersetzt / remplace / sustituye a / sostituisce 330 0088 20</b>
<b>LuK Repset:</b>	<b>630 2461 09 = 230 0028 10 + 329 0006 10 + 12 x M8 x 1.25 x 95mm bolts.</b> <b>630 2462 09 = 230 0028 10 + 329 0007 10 + 12 x M8 x 1.25 x 95mm bolts.</b>

\*\*

For model information please see LuK Catalogue / Die genaue Fahrzeugzuordnung entnehmen Sie bitte dem LuK-Katalog / Pour les informations le modèle veuillez consulter le catalogue LuK / Para obtener información sobre el modelo, rogamos consulte el catálogo de LuK / Per informazioni sul modello consultare il catalogo LuK

**230 0030 20**



**330 0088 20**



+




**230 0028 10**

**329 0006 10**



+



**630 2461 09**

Issue Level 2

**LuK Aftermarket Service UK Ltd.**  
Holme Lacy Road, Rotherwas  
HR2 6LA Hereford · The United Kingdom  
Phone: +44 1432 264264 · Fax +44 1432 275146  
e-mail: LuK-AS.uk.pm@schaeffler.com  
**A Member of the Schaeffler Group**

