

# SERVICE - INFO



**LuK Nr: 228 0072 10 – 280mm TGU6**

**Bulletin 988 2001 110**

**STEYR – 8055, 8060N, 8070N**

|                    |   |
|--------------------|---|
| <b>Info:</b>       | <b>228 0072 10 Replaces / ersetzt / remplace / sustituye a / sostituisce 228 0072 21</b>            |
| <b>(GB)</b>        | Bolts 6 x M8 x 1.25 x 95mm are supplied to fit new LuK clutch 228 0072 10.                          |
| <b>(D)</b>         | Schrauben 6 x M8 x 1.25 x 95mm passend für die neue LuK-Kupplung 228 0072 10.                       |
| <b>(F)</b>         | Les boulons 6 x M8 x 1.25 x 95mm sont fournis pour s'adapter au nouvel embrayage LuK 228 0072 10.   |
| <b>(E)</b>         | Los tornillos 6 x M8 x 1.25 x 95mm se distribuyen para el nuevo modelo de embrague LuK 228 0072 10. |
| <b>(I)</b>         | Bulloni 6 x M8 x 1.25 x 95mm in dotazione per la nuova frizione LuK 228 0072 10.                    |
| <b>Luk Repset:</b> | 628 1358 09 = <b>228 0072 10</b> [328 0109 10] + 328 0108 10 + 6 x M8 x 1.25 x 95mm                 |

**228 0072 21**



**228 0072 10**



Issue Level 2

**LuK Aftermarket Service UK Ltd.**  
Holme Lacy Road, Rotherwas  
HR2 6LA Hereford · The United Kingdom  
Phone: +44 1432 264264 · Fax +44 1432 275146  
e-mail: LuK-AS.uk.pm@schaeffler.com  
**A Member of the Schaeffler Group**

