

# SERVICE - INFO



**LuK Nr: 630 2461 09 – 280/295mm TGU6**

**Bulletin 988 2000 990**

**STEYR – M975, M986, 955, 964, 970E, 975 & 8070**

<b>Info:</b>	<b>630 2461 09 Replaces / ersetzt / remplace / sustituye a / sostituisce 230 0030 20 + 330 0088 20</b>
<b>LuK Repset:</b>	<b>630 2461 09 = 230 0028 10 + 329 0006 10 + 12 x M8 x 1.25 x 95mm bolts.</b>

\*\*For model information please see LuK Catalogue / Die genaue Fahrzeugzuordnung entnehmen Sie bitte dem LuK-Katalog / Pour les informations le modèle veuillez consulter le catalogue LuK / Para obtener información sobre el modelo, rogamos consulte el catálogo de LuK / Per informazioni sul modello consultare il catalogo LuK

**230 0030 20**




**330 0088 20**




+



**230 0028 10**



**329 0006 10**



+



**630 2461 09**

Subject to technical changes  
© 2011 Schaeffler Automotive Aftermarket

Issue Level 3 – 14/07/2011

**For further information:**

Phone: +44 (0) 14 32 264 264\*  
Fax: +44 (0) 14 32 375 760  
hfd-pm@schaeffler.com  
www.Schaeffler-Aftermarket.com  
\* Calls from within the UK 08457 001100

