

SERVICE - INFO



LuK Nr: 500 0058 10

Bulletin 988 2000 880

MERCEDES-BENZ UNIMOG / MB TRAC**

(GB)	Do not use 500 0058 10, only use 500 0634 00 for Mercedes-Benz Unimog / MB Trac models** using LuK 131 0202 20 / 233 0001 14 / 235 0007 14.
(D)	Nicht 500 0058 10 verwenden. Nur 500 0634 00 bei Mercedes-Benz-Unimog/MB Trac-Modellen** mit LuK 131 0202 20 / 233 0001 14 / 235 0007 14 einbauen.
(F)	N'utilisez pas la butée 500 0058 10, utilisez seulement la butée 500 0634 00 pour les modèles** Mercedes-Benz Unimog / MB Trac montés avec les références LuK 131 0202 20 / 233 0001 14 / 235 0007 14.
(E)	No utilice 500 0058 10, utilice sólo 500 0634 00 para modelos Mercedes-Benz Unimog / MB Trac** que utilizan LuK 131 0202 20 / 233 0001 14 / 235 0007 14.
(I)	Non utilizzare 500 0058 10, utilizzare solo 500 0634 00 per i modelli Mercedes-Benz Unimog / MB Trac** con LuK 131 0202 20 / 233 0001 14 / 235 0007 14.
LuK Repsets:	633 1401 09 = 233 0001 14 [331 0006 16] + 333 0001 13 635 1402 09 = 235 0007 14 [333 0139 10] + 335 0092 13

**For model information please see LuK Catalogue / Die genaue Fahrzeugzuordnung entnehmen Sie bitte dem LuK-Katalog / Pour les informations le modèle veuillez consulter le catalogue LuK / Para obtener información sobre el modelo, roqamos consulte el catálogo de LuK / Per informazioni sul modello consultare il catalogo LuK

500 0058 10



500 0634 00



Issue Level 3

LuK Aftermarket Service UK Ltd.
Holme Lacy Road, Rotherwas
HR2 6LA Hereford · The United Kingdom
Phone: +44 1432 264264 · Fax +44 1432 275146
e-mail: LuK-AS.uk.pm@schaeffler.com
A Member of the Schaeffler Group

