

Eicher**

Bulletin 9882001130

LuK Nr: 328 0155 17 – 280 USF 1 1/8 x 10

Info:	328 0155 17 replaces / ersetzt / remplace / sustituye a / sostituisce 328 0123 16
Luk Repset:	628 1374 09 = 228 0019 12 + [328 0049 16] + 328 0155 17 628 1408 09 = 228 0018 11 + [328 0048 16] + 328 0155 17

** For model information please see LuK Catalogue / Die genaue Fahrzeugzuordnung entnehmen Sie bitte dem LuK-Katalog / Pour les informations sur le modèle, veuillez consulter le catalogue LuK / Para obtener información sobre el modelo, rogamos consulte el catálogo de LuK / Per informazioni sul modello consultare il catalogo LuK



Issue Level 1 09/08
The right to make technical changes is reserved
© 2008 LuK-Aftermarket Service oHG

LuK Aftermarket Service UK Ltd.
Holme Lacy Road, Rotherwas
HR2 6LA Hereford · The United Kingdom
Phone: +44 1432 264264 · Fax +44 1432 275146
e-mail: LuK-AS.uk.pm@schaeffler.com
A Member of the Schaeffler Group

