

# SERVICE - INFO



**LuK Nr: 131 0038 11 – 305mm DBFR**

**Bulletin 988 2000 580**

**CASE IH – 74, 84, 85, 95, 3200 & 4200 Series**

<b>Info:</b>	<b>131 0038 11 replaces / ersetzt / remplace / sustituye a / sostituisce 131 0038 10</b>
<b>(GB)</b>	Please ensure that the flywheel is machined to a pot depth of 35.9mm, [1.413“].
<b>(D)</b>	Das Schwungrad ist auf eine Tiefe von 35.9mm, [1.413“] auszdrehen, siehe unten.
<b>(F)</b>	Veuillez vous assurer que le volant-moteur est rectifié à une profondeur de 35.9mm, [1.413“].
<b>(E)</b>	Asegúrese de que el volante está mecanizado hasta una profundidad de 35.9mm, [1.413“].
<b>(I)</b>	Controllare che il volano venga rettificato a una profondità di 35.9mm, [1.413“].
<b>LuK Repsets:</b>	631 1067 19 = <b>131 0038 11</b> + 331 0154 11 631 1067 10 = <b>131 0038 11</b> + 331 0154 11 + 500 1046 50 + 410 0026 00
	<b>131 0038 11 = 131 0038 12 + 434 0342 10</b>

**131 0038 10**

**1970876C1**

**131 0038 11**

**434 0342 10**



Subject to technical changes  
© 2011 Schaeffler Automotive Aftermarket

Issue Level 5 – 14/07/2011

**For further information:**

Phone: +44 (0) 14 32 264 264\*  
Fax: +44 (0) 14 32 375 760  
hfd-pm@schaeffler.com  
www.Schaeffler-Aftermarket.com  
\* Calls from within the UK 08457 001100

