

# SERVICE - INFO



**LuK Nr: 131 0017 11 – 305mm DBFR**

**Bulletin 988 2000 830**


**STEYR – 295, 60, 658, 760 & 768**

<b>Info:</b>	<b>131 0017 11 replaces / ersetzt / remplace / sustituye a / sostituisce 131 0017 10</b>
<b>(GB)</b>	Bolts M8 x 1.25 x 20mm are supplied to fit new LuK clutch 131 0017 11.
<b>(D)</b>	Schrauben M8 x 1,25 x 20mm passend für die neue LuK-Kupplung 131 0017 11.
<b>(F)</b>	Les boulons M8 x 1,25 x 20mm sont fournis pour s'adapter au nouvel embrayage LuK 131 0017 11.
<b>(E)</b>	Los tornillos M8 x 1,25 x 20 mm se distribuyen para el nuevo modelo de embrague LuK 131 0017 11.
<b>(I)</b>	Bulloni M8 x 1,25 x 20mm in dotazione per la nuova frizione LuK 131 0017 11.

**131 0017 10**



**131 0017 11**



Issue Level 2

**LuK Aftermarket Service UK Ltd.**  
Holme Lacy Road, Rotherwas  
HR2 6LA Hereford · The United Kingdom  
Phone: +44 1432 264264 · Fax +44 1432 275146  
e-mail: LuK-AS.uk.pm@schaeffler.com  
**A Member of the Schaeffler Group**

