

SERVICE - INFO



LuK Nr: 228 0046 10 – 280mm TGU6

Bulletin 988 2000 970

STEYR – 8060, 8070

Info:	228 0046 10 Replaces / ersetzt / remplace / sustituye a / sostituisce 228 0046 21
(GB)	Bolts 6 x M8 x 1.25 x 95mm are supplied to fit new LuK clutch 228 0046 10.
(D)	Schrauben 6 x M8 x 1.25 x 95mm passend für die neue LuK-Kupplung 228 0046 10.
(F)	Les boulons 6 x M8 x 1.25 x 95mm sont fournis pour s'adapter au nouvel embrayage LuK 228 0046 10.
(E)	Los tornillos 6 x M8 x 1.25 x 95mm se distribuyen para el nuevo modelo de embrague LuK 228 0046 10.
(I)	Bulloni 6 x M8 x 1.25 x 95mm in dotazione per la nuova frizione LuK 228 0046 10.
Luk Repset:	628 1386 09 = 228 0046 10 [328 0109 10] + 328 0108 10 + 6 x M8 x 1.25 x 95mm

228 0046 21



228 0046 10



Subject to technical changes
© 2011 Schaeffler Automotive Aftermarket

Issue Level 3 – 14/07/2011

For further information:

Phone: +44 (0) 14 32 264 264*
Fax: +44 (0) 14 32 375 760
hfd-pm@schaeffler.com
www.Schaeffler-Aftermarket.com
* Calls from within the UK 08457 001100

