

SERVICE - INFO



LuK Nr: 131 0017 11 – 305mm DBFR

Bulletin 988 2000 830


STEYR – 295, 60, 658, 760 & 768

Info:	131 0017 11 replaces / ersetzt / remplace / sustituye a / sostituisce 131 0017 10
(GB)	Bolts M8 x 1.25 x 20mm are supplied to fit new LuK clutch 131 0017 11.
(D)	Schrauben M8 x 1,25 x 20mm passend für die neue LuK-Kupplung 131 0017 11.
(F)	Les boulons M8 x 1,25 x 20mm sont fournis pour s'adapter au nouvel embrayage LuK 131 0017 11.
(E)	Los tornillos M8 x 1,25 x 20 mm se distribuyen para el nuevo modelo de embrague LuK 131 0017 11.
(I)	Bulloni M8 x 1,25 x 20mm in dotazione per la nuova frizione LuK 131 0017 11.

131 0017 10



131 0017 11



Subject to technical changes
© 2011 Schaeffler Automotive Aftermarket

Issue Level 3 – 14/07/2011

For further information:

Phone: +44 (0) 14 32 264 264*
Fax: +44 (0) 14 32 375 760
hfd-pm@schaeffler.com
www.Schaeffler-Aftermarket.com
* Calls from within the UK 08457 001100

