

# SERVICE - INFO



**LuK Nr: 131 0038 11 – 305mm DBFR**

**Bulletin 988 2000 580**

**CASE IH – 74, 84, 85, 95, 3200 & 4200 Series**

<b>Info:</b>	<b>131 0038 11 replaces / ersetzt / remplace / sustituye a / sostituisce 131 0038 10</b>
<b>(GB)</b>	Please ensure that the flywheel is machined to a pot depth of 35.9mm, [1.413"].
<b>(D)</b>	Das Schwungrad ist auf eine Tiefe von 35.9mm, [1.413"] auszdrehen, siehe unten.
<b>(F)</b>	Veillez vous assurer que le volant-moteur est rectifié à une profondeur de 35.9mm, [1.413"].
<b>(E)</b>	Asegúrese de que el volante está mecanizado hasta una profundidad de 35.9mm, [1.413"].
<b>(I)</b>	Controllare che il volano venga rettificato a una profondità di 35.9mm, [1.413"].
<b>LuK Repsets:</b>	631 1067 19 = <b>131 0038 11</b> + 331 0154 11 631 1067 10 = <b>131 0038 11</b> + 331 0154 11 + 500 1046 50 + 410 0026 00
	<b>131 0038 11 = 131 0038 12 + 434 0342 10</b>

**131 0038 10**

**1970876C1**

**131 0038 11**

**434 0342 10**



Issue Level 4

LuK Aftermarket Service UK Ltd.  
Holme Lacy Road, Rotherwas  
HR2 6LA Hereford · The United Kingdom  
Phone: +44 1432 264264 · Fax +44 1432 275146  
e-mail: LuK-AS.uk.pm@schaeffler.com  
A Member of the Schaeffler Group

