

SERVICE - INFO



LuK Nr: 228 0050 10 – 225/280mm SBA3

Bulletin 988 2000 610

NEW HOLLAND FORD – 2000, 3000 & 4000 Series

Info:	228 0050 10 Replaces / Ersetzt / remplace la / Sustituye a / Sostituisce 228 0050 51
-------	--

228 0050 51



228 0050 10



Issue Level 4

LuK Aftermarket Service UK Ltd.
Holme Lacy Road, Rotherwas
HR2 6LA Hereford · The United Kingdom
Phone: +44 1432 264264 · Fax +44 1432 275146
e-mail: LuK-AS.uk.pm@schaeffler.com
A Member of the Schaeffler Group

