

# SERVICE - INFO



**LuK Nr: 133 0007 10 – 330mm DGFO**

**Bulletin 988 2002 970**


**MF\*\***

<b>Info:</b>	<b>New design / Neues Design / Nouvelle conception / Nuevo diseño / Nuovo disegno</b>
<b>LuK Repset:</b>	<p>633 1122 09 = 133 0007 10 + 333 0052 46</p> <p>633 1122 19 = 133 0007 10 + 333 0052 41</p> <p>633 1124 09 = 133 0007 10 + 333 0050 40</p> <p>633 1124 19 = 133 0007 10 + 333 0050 46</p>

\*\* For model information please see LuK Catalogue / Die genaue Fahrzeugzuordnung entnehmen Sie bitte dem LuK-Katalog / Pour les informations le modèle veuillez consulter le catalogue LuK / Para obtener información sobre el modelo, rogamos consulte el catálogo de LuK / Per informazioni sul modello consultare il catalogo LuK

**Schraubenfeder  
Coil Spring  
Ressort helicoidal  
Resorte helicoidal  
Molia elicoidale**

**Tellerfeder  
Diaphragm spring  
Diaphragme  
Diafragma  
Molla a diaframma**



Subject to technical changes  
© 2011 Schaeffler Automotive Aftermarket

Issue Level 1 –27/06/2011

**For further information:**

Phone: +44 (0) 14 32 264 264\*  
 Fax: +44 (0) 14 32 375 760  
 hfd-pm@schaeffler.com  
 www.Schaeffler-Aftermarket.com  
 \* Calls from within the UK 08457 001100

