

SERVICE - INFO

John Deere – 500 0076 11

TBI_JD5000076

500 0076 11 Replaces / Ersetzt / remplace la réf. / Sostituye a / Sostituisce 500 0139 20

The transmission release bearing with carrier **500 0139 20** for John Deere applications is no longer available. LuK will now only supply the release bearing **500 0076 11** to repair existing carriers.



500 0139 20



500 0076 11

Subject to technical changes
© 2011 Schaeffler Automotive Aftermarket

Issue 1 – 12/01/2012

For further information:

Phone: +44 (0) 14 32 264 264*
Fax: +44 (0) 14 32 375 760
hfd-pm@schaeffler.com
www.Schaeffler-Aftermarket.com
* Calls from within the UK 08457 001100

