

SERVICE - INFO



LuK Nr: 228 0050 10 – 225/280mm SBA3

Bulletin 988 2000 610

NEW HOLLAND FORD – 2000, 3000 & 4000 Series

Info:	228 0050 10 Replaces / Ersetzt / remplace la / Sustituye a / Sostituisce 228 0050 51
--------------	--

228 0050 51



228 0050 10



Subject to technical changes
© 2011 Schaeffler Automotive Aftermarket

Issue Level 5 – 14/07/2011

For further information:

Phone: +44 (0) 14 32 264 264*
Fax: +44 (0) 14 32 375 760
hfd-pm@schaeffler.com
www.Schaeffler-Aftermarket.com
* Calls from within the UK 08457 001100

